














ZPOMALOVACÍ PRAHY - PLÁN SPOTŘEBY DÍLŮ

Montážní materiál	Délka prahu		Počet dílů			Schéma pokládky
	celková	efektivní	průběžný černý	průběžný žlutý	koncový žlutý	
ks	mm	mm	ks	ks	ks	
8	930	500	1	0	2	
12	1430	1000	1	1	2	
16	1930	1500	2	1	2	
20	2430	2000	2	2	2	
24	2930	2500	3	2	2	
28	3430	3000	3	3	2	
32	3930	3500	4	3	2	
36	4430	4000	4	4	2	
40	4930	4500	5	4	2	
44	5430	5000	5	5	2	
48	5930	5500	6	5	2	
52	6430	6000	6	6	2	
56	6930	6500	7	6	2	
60	7430	7000	7	7	2	
64	7930	7500	8	7	2	
68	8430	8000	8	8	2	